


Your Company Name Here



Demonstration Version *Home Inspection Report*



555 Anywhere USA

Typical, US

Demonstration Version

Table of Contents

PROPERTY INSPECTION REPORT	2
I. STRUCTURAL SYSTEMS	4
II. ELECTRICAL SYSTEMS	8
III. HEATING, VENTILATION, AND AIR-CONDITIONING SYSTEMS	9
IV. PLUMBING SYSTEM	11
V. APPLIANCES	12
VI. OPTIONAL SYSTEMS	13
Pre-Inspection Agreement	14
Summary	16

**Demonstration
Version**

**Demonstration
Version**

Your Company Name Here

PROPERTY INSPECTION REPORT

Prepared For: Bob Everybody
Concerning: 555 Anywhere Street Typical, US
Inspection Date: 1/28/2016
By: Inspector Name: Demonstration Inspector License Number: 6199 Date:
Signature:
Phone: E-Mail:

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement contact, order label and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any sellers disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations in writing from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in their home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- * malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- * malfunctioning arc fault protection (AFCI) devices;
- * ordinary glass in locations where modern construction techniques call for safety glass;
- * malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- * malfunctioning carbon monoxide alarms;
- * excessive spacing between balusters on stairways and porches;
- * improperly installed appliances;
- * improperly installed or defective safety devices;
- * lack of electrical bonding and grounding; and
- * lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as those the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Version

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation: Post Tension Cable

Comments: Post Tension Cable foundation Appears to be functioning as intended at the time of this inspection. This is a cursory and visual observation of the conditions and circumstances present at the time of this inspection.

The foundation has had some settlement, the amount of settlement observed is not uncommon to see in this region. This is a cursory and visual observation of the conditions and circumstances present at the time of this inspection.


Corner pops were observed at the foundation corners. This is a common condition to observe with slab on grade foundations. Cosmetic improvements can be undertaken, but are not required

Notice: Watering your foundation is very important in this region. Please refer to the foundation-watering program in the home maintenance guide.

Notice: Highly plastic clay soils, as are typically found in this region, exhibit a great amount of expansion and contraction with varying moisture contents. With this type of expansion and contraction of the soils, slab on grade homes and traditional/modern pier and beams homes will experience some degree of foundation distress. You should expect to see deflection cracks in the exterior brick veneer, sheetrock cracks and floor tile cracks.

Notice: The inspection of the foundation may show it to be functioning as intended or having movement typical to this region, at the time of the inspection. This does not guarantee the future life or failure of the foundation, but is a visual and cursory observation of the conditions and circumstances at the time of the inspection. The Inspector is not a structural engineer. This inspection is not an engineering report, and should not be considered one. If any cause of concern is noted on this report, or if you want further evaluation, you should consider an evaluation by an engineer.

B. Grading and Drainage - Comments: Flat. The general topography of the area is such that it will be difficult to control storm water runoff. During heavy rains the accumulation of storm water on the lot may be unavoidable.



C. Roof Covering Materials

Type of Roof Covering: Composition

Viewed from: Walking on Roof

Comments: Asphalt shingle Recommend monitoring the flashing from the main roof line to the patio covering. Although functioning at the time of this inspection these particular areas can be vulnerable over time and may need repairs in the future.

Recommend repairing the downspouts around the perimeter of the home to allow for proper discharge.

Final picture is just to illustrate that the profile vents were installed and appeared to be functioning as intended at the time of this inspection.

Due to the nature of the architectural design it is recommend the area above the front entrance be monitored for any future leaks due to the type of water discharge on this design of home. Although no moisture is noted at the time of this inspection it is recommended that the area be monitored and repaired if and when repairs are needed.

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

C. Roof Covering Materials (continued)



D. Roof Structures and Attics

Viewed from: Entering the attic

Approximate Average Depth of Insulation: 8 - 12 inches

Comments: 2x6 Truss Insulation levels are appropriate at the time of the inspection and no additional insulation is recommended at this time.

Recommend repairing the attic ladder to prevent an injury or damage.



Note: The inspector is not required to: determine the remaining life expectancy of the roof covering; inspect the roof from the roof level if, in the inspectors reasonable judgment, the inspector cannot safely reach; stay on the roof or significant damage to the roof covering materials may result from walking on the roof; determine the number of layers of roof covering material; identify latent hail damage; or provide an exhaustive list of locations of water penetrations or previous repairs.

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

E. Walls (Interior and Exterior) - Comments: Drywall/Brick, Nail pops are noted in various locations and should be repaired in the near future.

The interior of the home is need of cosmetic repairs, but overall structural condition appears to be functioning as intended at the time of this inspection.

It appears that the exterior brick line is over hanging from the original concrete layout. Does not appear to be affecting the performance of the foundation but recommend monitoring and repair as needed.



F. Ceilings and Floors - Comments: Drywall and Carpet, The exterior patio covering is showing signs of sagging which may be caused by water intrusion into the area or from improper installation. Further evaluation may be warranted to determine the actual cause.

Areas of separation area noted around various locations of the exterior trim and should be repaired.



G. Doors (Interior and Exterior) - Comments: Insulated steel doors, The dead bolt lock does not line up properly for the smaller garage door. Further adjustments are recommend to allow for ease of use.



H. Windows - Comments: Aluminum double hung, The northeast bedroom window has lost the seal causing a fogging effect between the two panes of glass. Further repairs are recommended.

Many of the windows are very difficult to open which may indicate that some lubrication is needed to allow for ease of use.

Notice: Signs of lost seals in the thermal pane windows may appear and disappear as temperature and humidity change. Some windows with lost seals may not be evident at the time of this inspection. Windows are only checked for obvious fogging. If some lost thermal pane window seals were noted, we recommend all windows be rechecked by a window specialist for further evaluation prior to closing

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

I. Stairways (Interior and Exterior) - Comments: Wood stairs with wood handrails, The stairway banister and rail are loose and should be secured.




Demonstration Version

J. Fireplaces and Chimneys - Comments: Prefab, Wood trim for the living room chimney is showing signs of rot and should be repaired in the near future.

Recommend cleaning out the living room fireplace.


Fresh air vent for the living room fireplace is damaged and should be replaced.



Vent for Master bedroom
Fireplace appliance



Living Room Fireplace



Chimney for Living Room
Fireplace

Demonstration Version

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

J. Fireplaces and Chimneys (continued)



Demonstration Version

K. Porches, Balconies, Decks, and Carports - Comments: Concrete, Appears to be functioning as intended at the time of this inspection.

L. Other - Comments:

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels - Comments: Copper, Appears to be functioning as intended at the time of this inspection.



Demonstration Version

B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: Copper

Comments: Copper Appears to be functioning as intended at the time of this inspection. However, loose outlets are noted in various locations and should be secured.

Kitchen Dining room switches showing no voltage, not functioning as expected at the time of this inspection.

Bulbs are burnt out in various locations and should be repaired.

Demonstration Version

Note: (ARC fault) All branch circuits that supply 120-volt, single-phase, 15- and 20-ampere outlets installed in bedrooms shall be protected by a combination type or branch/feeder type arc-fault circuit interrupter installed to provide protection of the entire branch circuit. Effective January 1, 2008, such arc-fault circuit interrupter devices shall be combination type for any homes built 2008 or newer

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

A. Heating Equipment

Type of Systems:

Energy Sources:

Comments: York Appears to be functioning as intended at the time of this inspection but due to the limitations of temperature restriction during the warmer winter it is difficult to get a representative reading on the air flow.

If additional concerns exist then a full evaluation should be completed by a qualified HVAC company.



Heating Equipment Specific Limitations:

The heating elements were tested for continuity but were not physically observed. The heating elements are located within the heater cabinet that would require specialized tools to access and reassemble. If the inspector were to remove the elements under these conditions, the HVAC warranty could be voided. If any concerns exist about the physical conditions of the heating elements, a Qualified HVAC Technician should be contracted prior to closing to fully evaluate to HVAC equipment.

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

B. Cooling Equipment

Type of Systems: Electric

Comments: Both units appeared to be functioning at the time of the inspection and appeared to be within the acceptable temperature differential guidelines of 15 degrees between the return and supply. If additional concerns exist regarding the integrity of the system then it is recommended that a full evaluation should be completed by a qualified HVAC company.



Cooling Equipment Specific Limitations

The indoor coils were not physically observed. The coils are located within the cabinet and/or plenum that would require specialized tools to access and reassemble. If the inspector were to remove the ducting and/or cut into the plenum under these conditions, the HVAC warranty could be voided. If any concerns exist about the physical condition of the indoor coils, a qualified HVAC Technician should be contracted prior to closing to fully evaluate to HVAC equipment.

Notice: Temperature differential readings are a fundamental standard for testing the proper operation of the cooling system. The normal acceptable range is considered approximately between 15 to 23 degrees F. total difference between the return air and supply air. Unusual conditions such as excessive humidity, low outdoor temperatures, and restricted airflow may indicate abnormal operation even through the equipment is functioning basically as designed and occasionally may indicate normal operation in spite of an equipment malfunction.

C. Duct Systems, Chases, and Vents - Comments: Insulated flex, Some noted bends in the flex duct was noted but

Client: Bob Everybody

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

C. Duct Systems, Chases, and Vents (continued)

overall appears to be functioning as intended at the time of this inspection.

IV. PLUMBING SYSTEM

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Front yard

Location of main water supply valve: Front yard

Static water pressure reading: 60-70 lbs

Comments: Copper Master bathroom leak noted around the shower head connection and should be repaired.

Chip is noted in the upstairs bathroom and should be repaired and caulk repairs are also recommended.



B. Drains, Wastes, and Vents - Comments: PVC, Appears to be functioning as intended at the time of this inspection.

No leaks were noted under any of the sink areas at the time of the inspection.

No backups are noted at the time of this inspection.

Notice: Reporting the condition of drains, wastes and vent piping that is not completely visible and/or accessible or; reporting any defect or deficiency that requires extended use of the system to develop or does not become evident during our limited cursory and visual survey is outside the scope of the inspection. This is a limited cursory and visual survey of the accessible general conditions and circumstances present at the time of this inspection. Opinions are based on general observations made without the use of specialized tools or procedures. Therefore, the opinions expressed are one of apparent conditions and not of absolute fact and are only good for the date and time of this inspection. The inspector will not be able to anticipate future events, conditions or changes in performance of any component or system due to changes in use or occupancy. The inspector makes no guarantee or warranty, express or implied, as to future performance of any item, system or component.

C. Water Heating Equipment

Energy Sources: Natural gas

Capacity: 50 gallon installed in 2011

Comments: A.O. Smith The inspector was unable to get the south water heater to ignite during the inspection. Recommend further repairs to get it functioning.

Life expectancy of a water heater, on average is about 7 to 12 years. Recommend monitoring and repair if and when repairs are needed.

One cannot predict the actual life expectancy of a water heater, so the client is encouraged to budget for a water heater.

D. Hydro-Massage Therapy Equipment - Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

D. Hydro-Massage Therapy Equipment (continued)

E. Other - Comments:

V. APPLIANCES

A. Dishwashers - Comments: Maytag, It sounds to be working properly at the time of this inspection.

B. Food Waste Disposers - Comments: Badger, Appears to be functioning as intended at the time of this inspection.

C. Range Hood and Exhaust Systems - Comments: Maytag, The circulating vent is part of the microwave and appears to be functioning as intended at the time of this inspection.

D. Ranges, Cooktops, and Ovens - Comments: Whirlpool, Maytag, Appears to be functioning as intended at the time of this inspection.


E. Microwave Ovens - Comments: Maytag

F. Mechanical Exhaust Vents and Bathroom Heaters - Comments:

G. Garage Door Operators - Comments: Genie, Linear, The garage door opener did not automatically reverse under resistance to closing. There is a serious risk of injury, particularly to children, under this condition. Improvement may be as simple as adjusting the sensitivity control on the opener. This should be repaired immediately.



Testing automatic reverse



I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

H. Dryer Exhaust Systems - Comments: Rigid metal, Small amount of blockage is noted in the dryer vent discharge and should be cleaned.

Appears that the discharge dryer line is within acceptable guidelines of 25 feet or less.



Demonstration Version

I. Other - Comments:

VI. OPTIONAL SYSTEMS

A. Landscape Irrigation (Sprinkler) Systems - Comments: Front and back yard, Recommend redirecting the spray away from the structure of the home and the fence

No coverage noted for the northwest corner of the yard. Further repairs are recommended.

10 zones present.



Demonstration Version

B. Swimming Pools, Spas, Hot Tubs, And Equipment

Type of Construction:
Comments:

Notice: Pool shell leaks and pool equipment backwash mode is not checked or inspected.

Notice: Evaluations of inline pool chlorinators are outside the scope of this inspection. Anytime there is an inline chlorinator in place, you are strongly encouraged to have the chlorinator fully evaluated by a qualified pool technician prior to closing.

Notice: Diving Boards and/or Slides; U.S. Consumer Product Safety Commission strongly recommends that all diving boards and/or slides be removed from pools for reasons of safety.

Notice: Per Texas Real Estate Commission Standards of Practice Full evaluation of the integrity of the pools gas heater heat exchanger requires dismantling of the furnace and is beyond the scope of a visual inspection.

C. Outbuildings - Comments:

D. Private Water Wells (A coliform analysis is recommended)

Type of Pump:
Type of Storage Equipment:
Comments:

Demonstration Version

E. Private Sewage Disposal (Septic) Systems

Type of System:
Location of Drain Field:
Comments:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

F. Other - Comments:

**Demonstration
Version**

**Demonstration
Version**

**Demonstration
Version**

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

Inspector Name: Mark Nation
Company Name: Cornerstone Inspections Inc.
Address: PO Box 1093
City State Zip: Arlington, TX 76013

Client Name: Bob Everybody

Property Address: 555 Anywhere Street
City State Zip: Typical, US, USA

Demonstration

AGREEMENTS AND LIMITATIONS

This Inspection Report covers only the items listed and only on the present condition of those items. This Inspection Report reflects only if the items inspected are observed to be "operable" or "inoperable" at the time of the inspection, that is, whether such items at this time are observed to serve the purpose for which they are ordinarily intended. Furthermore, this Inspection Report reflects only those items that are reasonably accessible and observable at the time of the inspection. NO REPRESENTATION OR COMMENT is made concerning any latent defect or defects not reasonably accessible or observable at the time of the inspection or of items which require the removal of major or permanent covering. NO REPRESENTATION IS MADE CONCERNING ANY OTHER CONDITION OR THE FUTURE PERFORMANCE OF ANY ITEM. NO REPRESENTATION IS MADE AS TO THE ITEMS NOT SPECIFICALLY COMMENTED UPON. ALL WARRANTIES, EXPRESSED OR IMPLIED, NOT SPECIFICALLY STATED HEREIN ARE EXCLUDED AND DISCLAIMED. If a comment is made concerning the condition of any item, the Buyer is URGED to contact a QUALIFIED SPECIALIST to make further inspections or evaluations of that item.

Buyer agrees to notify CornerStone Inspections in writing of any complains within (30) days of the inspection and must thereafter allow prompt re-inspection of the items under discussion; otherwise, the Buyer waives all claims for damages arising out of such complaint. If Buyer institutes any legal action concerning this inspection and fails to prevail on all of the causes of action alleged, Buyer shall be liable to CornerStone Inspections for any and all attorney's fees incurred in such action. Buyer, by accepting this Report or relying upon it in any way, expressly agrees to these Limitations and Disclaimers.

If a dispute arises out of or relate to the independent inspector's performance, and if, said dispute cannot be settled between the parties to this inspection by the standards themselves, the parties hereto hereby agree to settle the dispute by Binding Arbitration according to the Commercial Arbitration Rules of the American Arbitration Association, and judgment upon the award rendered by the arbitrator(s) may be entered in any event having jurisdiction thereof. The parties hereto further agree that a dispute submitted to one or their arbitrator(s), at either party's option, selected from the panel of arbitrators of the American Arbitration Association. All requests for arbitration shall be submitted to the Dallas Office of the American Arbitration Association and all arbitration administrating cost shall be borne equally by all parties to the dispute.

Note: For more information concerning your rights, contact the Consumer Protection Division of the Attorney General's Office, your local District or County, or the attorney of your choice.

This Inspection Report is prepared exclusively for the Buyer named and is not transferable to anyone in any form. Buyer gives permission for (inspector) to discuss report findings with Real Estate agents, specialist or repair persons for the sake of clarification.

I FULLY and COMPLETELY understand that this inspection is not a warranty or guarantee. This inspection is essentially visual, not technically exhaustive and does not imply every defect will be discovered.

Signature:

Inspection Date:

Demonstration

Version

Client: Bob Everybody

Summary


I. STRUCTURAL SYSTEMS

C. Roof Covering Materials Asphalt shingle, Recommend monitoring the flashing from the main roof line to the patio covering. Although functioning at the time of this inspection these particular areas can be vulnerable over time and may need repairs in the future.

Recommend repairing the downspouts around the perimeter of the home to allow for proper discharge.

Final picture is just to illustrate that the profile vents were installed and appeared to be functioning as intended at the time of this inspection.

Due to the nature of the architectural design it is recommended the area above the front entrance be monitored for any future leaks due to the type of water discharge on this design of home. Although no moisture is noted at the time of this inspection it is recommended that the area be monitored and repaired if and when repairs are needed. Types(s) of Roof Covering: Composition
Viewed From: Walking on Roof




D. Roof Structures and Attics 2x6 Truss, Insulation levels are appropriate at the time of the inspection and no additional insulation is recommended at this time.

Recommend repairing the attic ladder to prevent injury or damage. Viewed From: Entering the attic Approximate Average Depth of Insulation: 8 - 12 inches

Summary (continued)

D. Roof Structures and Attics (continued)



Demonstration
Version

E. Walls (Interior and Exterior) Drywall/Brick, Nail pops are noted in various locations and should be repaired in the near future.

The interior of the home is need of cosmetic repairs, but overall structural condition appears to be functioning as intended at the time of this inspection.

It appears that the exterior brick line is over hanging from the original concrete layout. Does not appear to be affecting the performance of the foundation but recommend monitoring and repair as needed.



F. Ceilings and Floors Drywall and Carpet, The exterior patio door is showing signs of sagging which may be caused by water intrusion into the area or from improper installation. Further evaluation may be warranted to determine the actual cause.

Areas of separation area noted around various locations of the exterior trim and should be repaired.



Demonstration
Version

G. Doors (Interior and Exterior) Insulated steel doors, The dead bolt lock does not line up properly for the smaller garage door. Further adjustments are recommended to allow for ease of use.

Demonstration
Version



Summary (continued)

H. Windows Aluminum double hung, The northeast bedroom window has lost the seal causing a fogging effect between the two panes of glass. Further repairs are recommended.

Many of the windows are very difficult to open which may indicate that some lubrication is needed to allow for ease of use.

I. Stairways (Interior and Exterior) Wood stairs with wood handrails, The stairway banister and rail are loose and should be secured.



Demonstration Version

J. Fireplaces and Chimneys Prefab, Wood trim for the living room chimney is showing signs of rot and should be repaired in the near future.

Recommend cleaning out the living room fireplace.

Fresh air vent for the living room fireplace is damaged and should be replaced.



Summary (continued)

J. Fireplaces and Chimneys (continued)



Demonstration
Version

IV. PLUMBING SYSTEM

A. Plumbing Supply, Distribution Systems and Fixtures Copper, Master bathroom leak noted around the shower head connection and should be repaired.

Chip is noted in the upstairs bathroom and should be repaired and caulk repairs are also recommended. Location of water meter: Front yard Location of main water supply valve: Front yard Static water pressure reading: 60-70 lbs



Demonstration
Version

C. Water Heating Equipment A.O. Smith, The inspector was unable to get the south water heater to ignite during the inspection. Recommend further repairs to get it functioning.

Life expectancy of a water heater, on average is about 7 to 12 years. Recommend monitoring and repair if and when repairs are needed.

One cannot predict the actual life expectancy of a water heater, so the client is encouraged to budget for a water heater. Energy Source: Natural gas Capacity: 50 gallon installed in 2011

V. APPLIANCES

A. Dishwashers Maytag, Unit sounds to be very loud/noisey at the time of this inspection.

G. Garage Door Operators Genie, Linear The garage door opener did not automatically reverse under resistance to closing. There is a serious risk of injury, particularly to children, if this condition is not corrected. Improvement may be as simple as adjusting the sensitivity control on the opener. This should be repaired immediately.


Demonstration
Version

Summary (continued)

G. Garage Door Operators (continued)



Testing automatic reverse



H. Dryer Exhaust Systems Rigid metal, small in diameter, locking is noted in the dryer vent discharge and should be cleaned.

Appears that the discharge dryer line is within acceptable guidelines of 25 feet or less.



VI. OPTIONAL SYSTEMS

A. Landscape Irrigation (Sprinkler) Systems Front and back yard, Recommend redirecting the spray away from the structure of the home and the fence

No coverage noted for the northwest corner of the yard. Further repairs are recommended.

10 zones present.

Demonstration Version

